

# General Environmental Incident Summary

**Incident:** 3307      **Date/Time Notice:** 5/2/2014      **DEM Incident No:**  
**Responsible Party:** ONEOK Rockies Midstream, LLC  
**Date Incident:** 5/1/2014      **Time Incident:** 1818      **Duration:** 1 minutes  
**County:** McKenzie      **Twp:** 149      **Rng:** 98      **Sec:** 5      **Qtr:**  
**Lat:** 47.76098      **Long:** -103.25710      **Method:** Interpolation from map  
**Location Description:** ONEOK Rockies Midstream, Bear Den to Cherry Creek Pipeline Project,  
within pipeline right-of-way approx 1.5 miles SE from Watford City.  
**Submitted By:** Loretta Earnest      **Affiliation:** ONEOK  
**Address:** 100 West 5th St  
**City:** Tulsa      **State:** OK      **Zip:**

## Received By:

## Contact Person:

2700 Lincoln Ave SE  
Sidney, MT

**Distance Nearest Occupied Building:** 0.25 Miles      **Release Contained:** Yes

**Type of Incident:** Construcion Equipment Failure

**Description of Released Contaminant:** hydraulic fluid

**Volume Spilled:** 3.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** No

## Cause of Incident:

Equipment failure during pipeline construction

## Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

The total amount of impacted soil from this release was approx 1 cubic yard. The likelihood of impact to surface or groundwater is none.

## Action Taken or Planned:

The site will be excavated by hand to remove all contaminated soil. It will then be bagged and relocated to the onsite secondary containment structure to await final disposal.

**Wastes Disposal Location:** It will be held onsite in a secondary containment structure until the construction contractor locates an approved disposal facility. The probable disposal location will be Indian Hills Disposal after soil sample lab results are reviewed and determined that this is the appropriate facility.

**Agencies Involved:**

**Updates**

---

**Date:** 5/2/2014      **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Hydraulic oil release during pipeline construction. Response is good according to the report. Followup is necessary, however.

---

**Date:** 5/8/2014      **Status:** Inspection

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

I arrived at the site. The weather was 45 °F, with wind from the northeast at 10-15 mph. Pipeline project south of Watford City; this project runs along the south side of 24th Street NW. I drove from Highway 85 for 2 miles following the pipeline project. The project has been completed, and the dirt is leveled off. I could not see any place where spill occurred. No further followup needed at this time.